IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No	6,535,780
Confirmation No.	7801
Issue Date	March 18, 2003
Inventorship	Anderson et al.
Applicant	
Group Art Unit	
Examiner	
Attorney's Docket No.	
m: 1	

Title: HIGH SPEED PROGRAMMER SYSTEM

REQUEST FOR CERTIFICATE OF CORRECTION

UNDER 37 CFR 1.323

15

5

10

To: Honorable Commissioner of Patents

P.O. Box 1450

Alexandria, VA 22313-1450

20

Lance R. Sadler (Tel. 509-755-7262; Fax 509-755-7252)

Sadler, Breen, Morasch & Colby, p.s. 422 W. Riverside Avenue, Suite 424

Spokane, WA 99201

Customer No. 75671

25

30

Sir:

From:

We respectfully request that a Certificate of Correction of Applicant's mistake be issued in accord with enclosed form PTO-1050. The errors listed in form PTO-1050 are believed to be of a clerical or typographical nature, or of minor character, which was not the fault of the Patent and Trademark Office. Further, the proposed corrections are not believed to constitute new matter or require reexamination. of forth addition, we are aware the required fee set in 37 CFR 1.20(a) for providing a correction of applicant's mistake. Accordingly, the

1

SBMC, p.s.

Commissioner is hereby authorized to charge any fee or credit any overpayments to Deposit Account No. 50-4143 of Sadler, Breen, Morasch & Colby.

We respectfully submit that error is present in the printed patent and that correction thereof in accord with enclosed form PTO-1050 is required to prevent any misunderstanding.

Respectfully Submitted,

10

15

5

Date: 8/26/2008 By: ___/Lance R. Sadler/

Lance R. Sadler Reg. No. 38,605

Attorney for Applicant

Sadler, Breen, Morasch & Colby, PS 422 W. Riverside Avenue, Suite 424

Spokane, Washington 99201 Telephone: (509) 755-7254 Facsimile: (509) 755-7252

20

SBMC, p.s. 2

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,535,780 Page <u>1</u> of <u>1</u>

APPLICATION NO.: 09/471,675

ISSUE DATE: March 18, 2003

INVENTOR(S) : George Leland Anderson et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 4, line 23, before "converter" delete "digitalto-analog" and insert - - digital-to-analog - -, therefor.

In column 4, line 26, before "the processor" delete "amplifer" and insert - - amplifier - -, therefor.

In column 9, line 8, before "have" insert - - may - -.

In column 11, line 61, before "circuit" delete "sources" and insert - - source - -, therefor.

In column 11, line 46, before "buffer" delete "the" and insert - - a - -, therefor.

In column 12, line 45, after "the" delete "amplifer" and insert - - amplifier - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sadler, Breen, Morasch & Colby 422 W. Riverside Ave., Suite 424 Spokane, WA 99201

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.